

Liaison Committee Report 23 Jan. 2019

Work to date

- Noise and dust monitoring, no complaints received. Additional measures to control dust emissions from the Coal Preparation Area, 6m high fence with debris netting attached presently being erected.
- Excavation operations in recent weeks concentrated on the second coal seam, Fivequarter. The rock above the Fivequarter coal seam is hard but excavators managing to dig it. The Fivequarter coal seam has previously been worked by Deep Miners.
- Coal sales from site continue.
- The remedial work to the outer face of Overburden Mound 1 completed. Overburden Mound 1 has been extended along the north eastern boundary.
-

Future work

- Remedial work to road surface to site entrance and radius from the A690, discussions with the Highways Dept. regarding traffic management ongoing.
- Continue to excavate overburden, extend Overburden Mound 1 towards north eastern side of site and recover coal progressing as site design.